



Date: 05/07/53
Flight/Frame(s): AXL-5M-48, AXL-5M-49
Source: USDA photo via
County of San Bernardino Flood Control District
825 E. Third Street
San Bernardino, CA 92415-0835

FIGURE 3-12
AERIAL PHOTOGRAPH
MAY 7, 1953

RCRA FACILITY INVESTIGATION (RFI)
PG&E TOPOCK COMPRESSOR STATION
NEEDLES, CALIFORNIA

CH2MHILL



Date: 05/24/55
Roll/Frame(s): 55W 8015, 8016
Source: NOAA National Geodetic Survey, SSMC#3
Information Services Branch, N/NGS12
1315 East West Highway
Silver Spring, MD 20910

FIGURE 3-13
AERIAL PHOTOGRAPH
MAY 24, 1955

RCRA FACILITY INVESTIGATION (RFI)
PG&E TOPOCK COMPRESSOR STATION
NEEDLES, CALIFORNIA

CH2MHILL




Date: 05/19/55
Roll/Frame(s): N/A; Oblique view to northeast
Source: PG&E

FIGURE 3-14
AERIAL PHOTOGRAPH
MAY 19, 1955

RCRA FACILITY INVESTIGATION (RFI)
PG&E TOPOCK COMPRESSOR STATION
NEEDLES, CALIFORNIA

CH2MHILL



Date: 05/19/55
Roll/Frame(s): N/A; Oblique view to northwest
Source: PG&E

FIGURE 3-15
AERIAL PHOTOGRAPH
MAY 19, 1955

RCRA FACILITY INVESTIGATION (RFI)
PG&E TOPOCK COMPRESSOR STATION
NEEDLES, CALIFORNIA

CH2MHILL



Date: 11/04/61
Roll/Frame(s): 61S 7907
Source: NOAA National Geodetic Survey, SSMC#3
Information Services Branch, N/NGS12
1315 East West Highway
Silver Spring, MD 20910

FIGURE 3-16
AERIAL PHOTOGRAPH
NOVEMBER 04, 1961

RCRA FACILITY INVESTIGATION (RFI)
PG&E TOPOCK COMPRESSOR STATION
NEEDLES, CALIFORNIA

CH2MHILL